

Addendum #4 to SJPC-22-60 (Shed 1 Roof) - August 5, 2022

Questions from Potential Bidders

Q1: In reviewing the drone photos for this project, we can not determine the configuration of the existing cricketing along the long edges that must be removed. Can you advise of the construction? Should we figure it is a wood structure that must be torn-out, or structural steel?

A1: The construction of cricketing for existing roof drainage to be removed is unknown.

Q2: Detail 2/D1 shows wall panels up the side walls. A top termination is not shown. How should these panels be terminated?

A2: Wall panel termination at the top edge of side wall panels to be replaced as a part of the gable wall flashing shall be consistent with the approved manufacturer's details for top of wall flashing terminations.