

**Amendment #4 to RFP: SJPC-CBRP6519 – CORRECTION**

Please note that the specification for the **36k Lifts' Coil Ram Size** was incorrectly listed as 89". **THE CORRECT COIL RAM SIZE FOR 36K LIFTS IS 60"**. We apologize for any inconvenience this may have caused.